



Western Michigan University
ScholarWorks at WMU

Legacy Scout Tickets from Pure Oil Company

8-20-2021

MGRRE_PureOilScoutTickets_Carpenter_2_21111007150000

MGRRE

Western Michigan University

Follow this and additional works at: <https://scholarworks.wmich.edu/pure>



Part of the Geology Commons

WMU ScholarWorks Citation

MGRRE, "MGRRE_PureOilScoutTickets_Carpenter_2_21111007150000" (2021). *Legacy Scout Tickets from Pure Oil Company*. 5161.

<https://scholarworks.wmich.edu/pure/5161>

This Document is brought to you for free and open access via ScholarWorks at WMU. It has been accepted for inclusion in Legacy Scout Tickets from Pure Oil Company by an authorized administrator of ScholarWorks at WMU. See the National Digital Catalogue - Science Base Catalogue for more collections submitted by MGRRE.



MGRRE_PureOilScoutTickets_Carpenter_2_21111007150000

API 21111007150000

Permit Number 715

Lease Name Carpenter

Well Number 2

County Midland

Township 14N

Range 02W

Section 7

2021 DEQ or Pure co_name Roosevelt Oil Company

Pure Number 51

Latitude 43.6144

Longitude -84.6067


WELL REPORT - OUTSIDE OPERATIONS

SERIAL NO. 51STATE Michigan PSH XX Midland
CO.OPERATOR Sias Oil Co.FARM Carpenter Hrs. WELL NO. 2TWP. Greendale S. 7 T. 14N R. 2W
SURVEYLOC. SW SWWILDCAT ☐ FIELD ☐ FIELD NAME _____

MAP NO. _____ CO-ORD. _____ ELEV. _____

STATUS Plugged and Abandoned 6-22-48.Total Depth 3590'.

NORTH

DATE 7-14-48 SCOUT H. J. G.

THE PURE OIL COMPANY

LOCATION REPORT

No. 51 ✓

DATE June 10th 1929

STATE Michigan COUNTY Midland DIST. Greendale SEC. 7 TOWN 14N RANGE 2W
 WELL No. 2 (SERIAL No. 51) FARM T.J. Carpenter Hrs 36.88 ACRES

NAME OF STREAM OR WATERS _____ QUADRANGLE SW-SWOPERATOR Sins Oil Co MAP Greendale Twp - Midland Co -330 Feet from North Line of Farm

" " East " " "

" " South " " "

330 " " West " " "

Feet from North Line of Section

" " East " " "

990 " " South " " "330 " " West " " "

LEGEND

O LOCATION

① RIG

⊕ DRILLING

⊗ GAS WELL

● OIL WELL

⦿ SMALL OIL WELL

⦿ DRY HOLE

⦿ DRY SHOWING OIL


⦿ DRY SHOWING GAS

⦿ ABANDONED LOCATION

⦿ ABANDONED GAS WELL

⦿ ABANDONED OIL WELL

NOTE: Below make tracing from map, (when no map is obtainable make sketch) showing farm, center of section, this location with measurements and also wells, dry holes, or other locations in the vicinity of this location. Make copy to keep for reference and send original to Columbus office.



REMARKS:

SIGNED

Superintendent or Foreman.

No. -51-

SIGNED _____ SUPT. OR FOREMAN