



Western Michigan University
ScholarWorks at WMU

Legacy Scout Tickets from Pure Oil Company

8-20-2021

**MGRRE_PureOilScoutTickets_Heilman, Arthur &
Nellie_1_21133089020000**

MGRRE
Western Michigan University

Follow this and additional works at: <https://scholarworks.wmich.edu/pure>



Part of the Geology Commons

WMU ScholarWorks Citation

MGRRE, "MGRRE_PureOilScoutTickets_Heilman, Arthur & Nellie_1_21133089020000" (2021). *Legacy Scout Tickets from Pure Oil Company*. 8233.
<https://scholarworks.wmich.edu/pure/8233>

This Document is brought to you for free and open access via ScholarWorks at WMU. It has been accepted for inclusion in Legacy Scout Tickets from Pure Oil Company by an authorized administrator of ScholarWorks at WMU. See the National Digital Catalogue - Science Base Catalogue for more collections submitted by MGRRE.



MGRRE_PureOilScoutTickets_Heilman, Arthur & Nellie_1_21133089020000

API 21133089020000

Permit Number 8902

Lease Name Heilman, Arthur & Nellie

Well Number 1

County Osceola

Township 18N

Range 10W

Section 19

2021 DEQ or Pure co_name Mid Michigan Gas well in Stray. Stratigraphic and production data.
orage Company

Pure Number 137

Latitude 43.9313772

Longitude -85.5500169

THE PURE OIL COMPANY

DATE August 27, 1941

LOCATION REPORT

No. 137

STATE Michigan COUNTY Osceola DIST. Lincoln TWP. Lincoln SEC. 19 TOWN 18 N RANGE 18 W
WELL No. 1 (SERIAL No. 137) FARM Arthur and Nellie Heilman ACRES

NAME OF STREAM OR WATERS QUADRANGLE C 32 SW SE


OPERATOR Ohio Weber Oil Company Map Lincoln Township, Osceola County

Feet from North Line of Farm
660 660 " " East " " "
330 330 " " South " " "
" " West " " "

Feet from North Line of Section
330 330 " " South " 1/4 "
660 660 " " West " " "

- Lincoln - Osceola
- yards
- LEGEND**
- LOCATION
 - ⊕ RIG
 - ⊕ DRILLING
 - ☀ GAS WELL
 - OIL WELL
 - SMALL OIL WELL
 - ⊙ DRY HOLE
 - DRY SHOWING OIL
 - ⊙ DRY SHOWING GAS
 - ⊙ ABANDONED LOCATION
 - ☀ ABANDONED GAS WELL
 - ABANDONED OIL WELL

NOTE: Below make tracing from map, (when no map is obtainable make sketch) showing farm, center of section, this location with measurements and also wells, dry holes, or other locations in the vicinity of this location.



REMARKS:

SIGNED

W

Superintendent or Foreman.

