



Western Michigan University
ScholarWorks at WMU

Legacy Scout Tickets from Pure Oil Company

8-20-2021

MGRRE_PureOilScoutTickets_Leininger,
Henry_1_21027081100000

MGRRE
Western Michigan University

Follow this and additional works at: <https://scholarworks.wmich.edu/pure>



Part of the Geology Commons

WMU ScholarWorks Citation

MGRRE, "MGRRE_PureOilScoutTickets_Leininger, Henry_1_21027081100000" (2021). *Legacy Scout Tickets from Pure Oil Company*. 11026.
<https://scholarworks.wmich.edu/pure/11026>

This Document is brought to you for free and open access via ScholarWorks at WMU. It has been accepted for inclusion in Legacy Scout Tickets from Pure Oil Company by an authorized administrator of ScholarWorks at WMU. See the National Digital Catalogue - Science Base Catalogue for more collections submitted by MGRRE.



MGRRE_PureOilScoutTickets_Leininger, Henry_1_21027081100000

API 21027081100000

Permit Number 8110

Lease Name Leininger, Henry

Well Number 1

County Cass

Township 07S

Range 14W

Section 18

2021 DEQ or Pure co_name Beam and Wilson, Oil Company

Pure Number 40

Latitude 41.8568

Longitude -85.97896

THE PURE OIL COMPANY

DATE October 17, 1940

LOCATION RECORD OF LOCATION REPORT OTHER OPERATORS

No. 40

STATE Michigan COUNTY Cass DIST. Calvin TWP. Calvin Division 18 SEC. 18 TOWN 7S RANGE 14W
WELL No. 1 (SERIAL No. 440) FARM Henry Leininger ACRES

NAME OF STREAM OR WATERS QUADRANGLE NE-SW-SE

OPERATOR Beam and Wilson Oil Company Map Calvin Township, Cass County

330 330 Feet from North Line of Farm

330 330 " " East " " "

" " South " " "

" " West " " "

Feet from North Line of Section

" " East " " "

990 990 " " South " 1/4

990 990 " " West " " "

Low

LEGEND

○ LOCATION

⊕ RIG

⊕ DRILLING

⊗ GAS WELL

● OIL WELL

● SMALL OIL WELL

⊗ DRY HOLE

⊗ DRY SHOWING OIL


⊗ DRY SHOWING GAS

⊗ ABANDONED LOCATION

⊗ ABANDONED GAS WELL

⊗ ABANDONED OIL WELL

NOTE: Below make tracing from map. (when no map is obtainable make sketch) showing farm, center of section, this location with measurements and also wells, dry holes, or other locations in the vicinity of this location.



REMARKS:

SIGNED

W

Superintendent or Foreman.

Signed D. C. Shackelford