



Western Michigan University
ScholarWorks at WMU

Legacy Scout Tickets from Pure Oil Company

8-20-2021

MGRRE_PureOilScoutTickets_Reed, Ray_1_21075076190000

MGRRE

Western Michigan University

Follow this and additional works at: <https://scholarworks.wmich.edu/pure>



Part of the Geology Commons

WMU ScholarWorks Citation

MGRRE, "MGRRE_PureOilScoutTickets_Reed, Ray_1_21075076190000" (2021). *Legacy Scout Tickets from Pure Oil Company*. 3822.

<https://scholarworks.wmich.edu/pure/3822>

This Document is brought to you for free and open access via ScholarWorks at WMU. It has been accepted for inclusion in Legacy Scout Tickets from Pure Oil Company by an authorized administrator of ScholarWorks at WMU. See the National Digital Catalogue - Science Base Catalogue for more collections submitted by MGRRE.



MGRRE_PureOilScoutTickets_Reed, Ray_1_21075076190000

API 21075076190000

Permit Number 7619

Lease Name Reed, Ray

Well Number 1

County Jackson

Township 04S

Range 02W

Section 13

2021 DEQ or Pure co_name Morency, Alfred G.

Pure Number 16

Latitude 42.11741

Longitude -84.48646

DATE May 15, 1940 Correction

LOCATION REPORT

No. 166STATE Michigan COUNTY Jackson DIST. Hanover SEC. 13 TOWN 4/S RANGE 2 W
WELL No. 1 (SERIAL No. 16) FARM Ray Reed ACRESNAME OF STREAM OR WATERS _____ QUADRANGLE SW-SW-SE-SEOPERATOR Alfred G. Morency Map Hanover Township, Jackson County
Alfred G. Morency Hanover - Jackson

Feet from North Line of Farm

" " East " " "

400 400 " " South " " "530 530 " " West " " "

Feet from North Line of Section

" " East " " "

400 400 " " South " " "530 530 " " West " " "

LEGEND

○ LOCATION

① RIG

⊕ DRILLING

☼ GAS WELL

● OIL WELL

● SMALL OIL WELL

⊙ DRY HOLE

● DRY SHOWING OIL


⊙ DRY SHOWING GAS

⊙ ABANDONED LOCATION

☼ ABANDONED GAS WELL

● ABANDONED OIL WELL

NOTE: Below make tracing from map, (when no map is obtainable make sketch) showing farm, center of section, this location with measurements and also wells, dry holes, or other locations in the vicinity of this location.

REMARKS: Correcting location. correcting location


SIGNED

Subintendent or Foreman.

| | | |
|-----|-----|---------------------------------|
| | | Feet from North Line of Farm |
| | " " | East " " " |
| 330 | 330 | " " South " " " |
| 330 | 330 | " " West " " " |
| | | Feet from North Line of Section |
| | " " | East " " " |
| 330 | 330 | " " South " 1/4 " |
| 330 | 330 | " " West " " " |

- LEGEND
- | | |
|------------------|----------------------|
| ○ LOCATION | ⊙ DRY HOLE |
| ⊕ RIG | ⬤ DRY SHOWING OIL |
| ⊕ DRILLING | ⊙ DRY SHOWING GAS |
| ⊙ GAS WELL | ⊙ ABANDONED LOCATION |
| ● OIL WELL | ⊙ ABANDONED GAS WELL |
| ⬤ SMALL OIL WELL | ⬤ ABANDONED OIL WELL |

NOTE: Below make tracing from map, (when no map is obtainable make sketch) showing farm, center of section, this location with measurements and also wells, dry holes, or other locations in the vicinity of this location.



REMARKS:

SIGNED W
Superintendent or Foreman.

Signed D. C. Shackelford