



Western Michigan University  
ScholarWorks at WMU

---

Legacy Scout Tickets from Pure Oil Company

---

8-20-2021

**MGRRE\_PureOilScoutTickets\_Peck, L. T.\_1\_21081072740000**

MGRRE

*Western Michigan University*

Follow this and additional works at: <https://scholarworks.wmich.edu/pure>



Part of the Geology Commons

---

#### **WMU ScholarWorks Citation**

MGRRE, "MGRRE\_PureOilScoutTickets\_Peck, L. T.\_1\_21081072740000" (2021). *Legacy Scout Tickets from Pure Oil Company*. 4305.

<https://scholarworks.wmich.edu/pure/4305>

This Document is brought to you for free and open access via ScholarWorks at WMU. It has been accepted for inclusion in Legacy Scout Tickets from Pure Oil Company by an authorized administrator of ScholarWorks at WMU. See the National Digital Catalogue - Science Base Catalogue for more collections submitted by MGRRE.



---

**MGRRE\_PureOilScoutTickets\_Peck, L. T.\_1\_21081072740000**

API 21081072740000

Permit Number 7274

Lease Name Peck, L. T.

Well Number 1

County Kent

Township 06N

Range 12W

Section 12

2021 DEQ or Pure co\_name Welsh Oil Company

Pure Number 427

Latitude 42.9158

Longitude -85.67219

THE PURE OIL COMPANY

DATE January 24, 1940

LOCATION REPORT

No. 427

STATE Michigan COUNTY Kent

DIST. Wyoming  
TWP. Wyoming  
PREC. L. T. Peck

SEC. 12 TOWN 6 N RANGE 12 W

WELL No. 1 (SERIAL No. 427) FARM \_\_\_\_\_ ACRES \_\_\_\_\_

NAME OF STREAM OR WATERS \_\_\_\_\_ QUADRANGLE NE-SW-SE


OPERATOR C. A. Welsh Map Wyoming Township, Kent County  
33330 C. A. Welsh Wyoming - Kent

\_\_\_\_\_ Feet from North Line of Farm  
33330 " " East " " "  
 \_\_\_\_\_ " " South " " "  
 \_\_\_\_\_ " " West " " "  
 \_\_\_\_\_ Feet from North Line of Section  
 \_\_\_\_\_ " " East " " "  
990990 " " South " " "  
990990 " " West " " 1/4

LEGEND

- LOCATION
- ⊙ RIG
- ⊕ DRILLING
- ☀ GAS WELL
- OIL WELL
- ⦿ SMALL OIL WELL
- ⊖ DRY HOLE
- ⊕ DRY SHOWING OIL
- ⊖ DRY SHOWING GAS
- ⊖ ABANDONED LOCATION
- ☀ ABANDONED GAS WELL
- ⦿ ABANDONED OIL WELL

NOTE: Below make tracing from map, (when no map is obtainable make sketch) showing farm, center of section, this location with measurements and also wells, dry holes, or other locations in the vicinity of this location.



REMARKS:

SIGNED

Superintendent or Foreman.

COMPLETION RECORD OF WELLS DRILLED BY OTHER OPERATORS

Michigan Producing Division

Date **March 13, 1940**

No. **427**

State **Mich.** County **Kent** ~~Butte~~ Twp. **Wyoming** Sec. **12** Twp. **6 N** Rge. **12 W**

Well No. **1** (Serial No.) ~~(County No.)~~ **427** Farm **L. T. Peck** Acres

Operator **C. A. Welsh** Information secured from ~~owner~~ **By Scouting Department**

Date well started **2-8-40** Dated well completed **3-7-40** Elevation **647.5**

PRODUCTION RECORD

1st 24 hours natural **Dry Hole**

2nd 24 hours natural

Date of shot No. of quarts From to From to

Date of acid No. of gallons

1st 24 hours after acid shot

2nd 24 hours after acid shot

FORMATION AND CASING RECORD

Formation	Top	Bottom	Top Pay	Bottom Pay	Remarks	Casing	
						Size	Set at
Marshall		4447				10"	60
Coldwater Line	809	820				8-1/4"	419
Red Rock	1090	1095					
" "	1173	1184					
Berea	1222	1237					
Antrim	1700	1781					
Traverse Line	1847	S.L.M.		1883	Water-1000 ft.		
Total Depth		1905					

Remarks

Signed

**D. C. Shackelford**