



Western Michigan University
ScholarWorks at WMU

Legacy Scout Tickets from Pure Oil Company

8-20-2021

MGRRE_PureOilScoutTickets_Campbell_11_21111047190000

MGRRE

Western Michigan University

Follow this and additional works at: <https://scholarworks.wmich.edu/pure>



Part of the Geology Commons

WMU ScholarWorks Citation

MGRRE, "MGRRE_PureOilScoutTickets_Campbell_11_21111047190000" (2021). *Legacy Scout Tickets from Pure Oil Company*. 5697.

<https://scholarworks.wmich.edu/pure/5697>

This Document is brought to you for free and open access via ScholarWorks at WMU. It has been accepted for inclusion in Legacy Scout Tickets from Pure Oil Company by an authorized administrator of ScholarWorks at WMU. See the National Digital Catalogue - Science Base Catalogue for more collections submitted by MGRRE.



MGRRE_PureOilScoutTickets_Campbell_11_21111047190000

API 21111047190000

Permit Number 4719

Lease Name Campbell

Well Number 11

County Midland

Township 13N

Range 01W

Section 17

2021 DEQ or Pure co_name Summit Petroleum Corporation

Pure Number 1004

Latitude 43.5213054

Longitude -84.4606812


WELL REPORT - OUTSIDE OPERATIONS

SERIAL NO. 1004STATE Michigan ~~PSHX~~ CO. MidlandOPERATOR Basin Oil CompanyFARM J. W. Campbell WELL NO. 11TWP. Porter S. 17 T. 13N R. 1WLOC. SE NE NWWILDCAT ☐ FIELD ☐ FIELD NAME _____

MAP NO. _____ CO-ORD. _____ ELEV. _____

STATUS Total Depth 3390'.Abandoned 8-14-38. To be used as a
Brine Disposal Well in Dundee.

NORTH

DATE 5-1-50 SCOUT H. J. G.

DATE December 16, 1937

LOCATION REPORT

No. 1004

STATE Michigan

COUNTY Midland

DIST. Porter
TWP. Porter
PREC. J. W. Campbell

SEC. 17

TOWN 13 N

RANGE 1 W

WELL No. 11 (SERIAL No. 1004) FARM

ACRES

NAME OF STREAM OR WATERS

QUADRANGLE SE-NE-NW

OPERATOR Roosevelt Oil Company

Map

Porter Township, Midland County

900 900

Feet from North Line of Farm

900 900

" " East " " "

" " South " " "

" " West " " "

1100 1100

Feet from North Line of Section

350 350

" " East 1/4 "

" " South " " "

" " West " " "

LEGEND

○ LOCATION

① RIG

⊕ DRILLING

☼ GAS WELL

● OIL WELL

◆ SMALL OIL WELL

⊙ DRY HOLE

◆ DRY SHOWING OIL


⊙ DRY SHOWING GAS

⊙ ABANDONED LOCATION

☼ ABANDONED GAS WELL

◆ ABANDONED OIL WELL

NOTE: Below make tracing from map, (when no map is obtainable make sketch) showing farm, center of section, this location with measurements and also wells, dry holes, or other locations in the vicinity of this location.



REMARKS:

SIGNED

Superintendent or Foreman.

No. 1004

D. C. Shackelford